SOLO GUITARS

GFK-10 WIRING DIAGRAM

= SOLDER JOINT

= HOT/LIVE/SIGNAL WIRE

= GROUND WIRE

NECK PICKUP

BRIDGE PICKUP

RUN GROUND WIRE TO BRIDGE

V1
500K Log

V2
500K Log

T1
500K Lin

T2
500K Lin

0.47uF

0.47uF

Solo

GUITARS™

Your Everything Guitar Company