


SOLO PRK Wiring Diagram

Grounding Pot 1
Bend one outer peg to the top of the pot. Then solder it in place.



Feed this Ground Wire into the Post For the Bridge



Bridge Signal Wire

Neck Signal Wire

Output Jack Signal Wire

- ■ ■ Ground Wire
- Signal Wire
- Solder Points

