


SOLO GUITARS

FYK-1 WIRING DIAGRAM

● = SOLDER JOINT

— = HOT/LIVE/SIGNAL WIRE

— = GROUND WIRE



RUN GROUND WIRE TO BRIDGE POST